


# Terminal Marking

---

## Terminal Group Marking

The terminal groups of the screw, spring cage and fast connection terminal blocks, which have a middle Zack strip groove, are marked with the group marker label GBS 5-25x12. Marking is done with labels for the laser printer (see CLIPLINE catalog), the thermal transfer printer (see CLIPLINE catalog) or manually with the M-PEN.



# Terminal Group Marking



## Technical data

**Group marker label,**  
snaps onto terminal center for screw, spring cage and fast connection  
terminal blocks, can be labeled with a 25 x 12 label (see CLIPLINE  
catalog) or manually with the M-PEN, in the foot part with ZB 6

**Material**  
**Inflammability class in acc. with UL 94**  
Temperature range [°C]  
**Color**  
**Components**

Type	Order No.	Pcs. Pkt.
GBS 5-25 x 12	08 10 58 8	100
PA V2 – 40 to + 100 gray free from silicone and halogen		